

Facility: Farb MS Report Type: Progress Report Date of Report: 5/9/2019

	Location	DWO No	Туре	Initial Result*	Action Taken**	Clearance Result
1	1 Admin/Kitchen/Library/Supply - Farb_01-01 First Aid Office, South Wall	DWO-367-001	Faucet	0.87		
2	1 Admin/Kitchen/Library/Supply - Farb_01-01 Office Workroom 1, South Wall	DWO-367-002	Faucet	1.61		
3	1 Admin/Kitchen/Library/Supply - Farb_01-01 Building Exterior, East Wall	DWO-367-003	Drinking Fountain Bubbler	0.45		
4	1 Admin/Kitchen/Library/Supply - Farb_01-01 Building Exterior, East Wall	DWO-367-004	Drinking Fountain Bubbler	0.61		
5	1 Admin/Kitchen/Library/Supply - Farb_01-01 Library Workroom 2, East Wall	DWO-367-005	Faucet	0.64		
6	1 Admin/Kitchen/Library/Supply - Farb_01-01 Kitchen, South Wall left	DWO-367-006	Faucet	3.97		
7	1 Admin/Kitchen/Library/Supply - Farb_01-01 Building Exterior, West Wall	DWO-367-007	Drinking Fountain Bubbler	1.61		
8	1 Admin/Kitchen/Library/Supply - Farb_01-01 Building Exterior, West Wall	DWO-367-008	Drinking Fountain Bubbler	<5		
9	1 Admin/Kitchen/Library/Supply - Farb_01-01 Building Exterior, West Wall	DWO-367-009	Drinking Fountain Bubbler	0.89		
10	2 Classrooms 21-26 - Farb_01-02 Classroom/Non-Standard - 21T, West Wall	DWO-367-010	Drinking Fountain Bubbler	5.37		
11	2 Classrooms 21-26 - Farb_01-02 Classroom/Non-Standard - 23T, South Wall	DWO-367-011	Drinking Fountain Bubbler	2.15		
12	2 Classrooms 21-26 - Farb_01-02 Classroom/Non-Standard - 24T, South Wall	DWO-367-012	Drinking Fountain Bubbler	2.60		
13	2 Classrooms 21-26 - Farb_01-02 Classroom/Non-Standard - 26T, East Wall	DWO-367-013	Drinking Fountain Bubbler	1.59		
14	2 Classrooms 21-26 - Farb_01-02 Building Exterior, South Wall	DWO-367-014	Drinking Fountain Bubbler	2.58		
15	2 Classrooms 21-26 - Farb_01-02 Building Exterior, South Wall	DWO-367-015	Drinking Fountain Bubbler	3.42		
16	2 Classrooms 21-26 - Farb_01-02 Building Exterior, South Wall	DWO-367-016	Drinking Fountain Bubbler	4.06		



Facility: Farb MS Report Type: Progress Report Date of Report: 5/9/2019

	Location	DWO No	Туре	Initial Result*	Action Taken**	Clearance Result
17	3 Classrooms 31-36 - Farb_01-03 Building Exterior, South Wall	DWO-367-017	Drinking Fountain Bubbler	1.64		
18	3 Classrooms 31-36 - Farb_01-03 Building Exterior, South Wall	DWO-367-018	Drinking Fountain Bubbler	2.13		
19	3 Classrooms 31-36 - Farb_01-03 Building Exterior, South Wall	DWO-367-019	Drinking Fountain Bubbler	2.34		
20	3 Classrooms 31-36 - Farb_01-03 Classroom/Non-Standard - 31T, West Wall	DWO-367-020	Drinking Fountain Bubbler	5.27		
21	3 Classrooms 31-36 - Farb_01-03 Classroom/Non-Standard - 33T, South Wall	DWO-367-021	Drinking Fountain Bubbler	2.04		
22	3 Classrooms 31-36 - Farb_01-03 Classroom/Non-Standard - 34T, South Wall	DWO-367-022	Drinking Fountain Bubbler	11.10		
23	3 Classrooms 31-36 - Farb_01-03 Classroom/Non-Standard - 36T, East Wall	DWO-367-023	Drinking Fountain Bubbler	2.57		
24	4 Classrooms 41-46 - Farb_01-04 Classroom/Non-Standard - 41T, North Wall	DWO-367-024	Drinking Fountain Bubbler	3.17		
25	4 Classrooms 41-46 - Farb_01-04 Classroom/Non-Standard - 43T, West Wall	DWO-367-025	Drinking Fountain Bubbler	6.10		
26	4 Classrooms 41-46 - Farb_01-04 Classroom/Non-Standard - 44T, West Wall	DWO-367-026	Drinking Fountain Bubbler	4.88		
27	4 Classrooms 41-46 - Farb_01-04 Classroom/Non-Standard - 46T, South Wall	DWO-367-027	Drinking Fountain Bubbler	4.14		
28	4 Classrooms 41-46 - Farb_01-04 Building Exterior, West Wall	DWO-367-028	Drinking Fountain Bubbler	<5		
29	4 Classrooms 41-46 - Farb_01-04 Building Exterior, West Wall	DWO-367-029	Drinking Fountain Bubbler	2.02		
30	4 Classrooms 41-46 - Farb_01-04 Building Exterior, West Wall	DWO-367-030	Drinking Fountain Bubbler	2.20		
31	5 Classrooms 51-56 - Farb_01-05 Building Exterior, West Wall	DWO-367-031	Drinking Fountain Bubbler	1.11		
32	5 Classrooms 51-56 - Farb_01-05 Building Exterior, West Wall	DWO-367-032	Drinking Fountain Bubbler	0.96		



Facility: Farb MS Report Type: Progress Report Date of Report: 5/9/2019

	Location	DWO No	Туре	Initial Result*	Action Taken**	Clearance Result
33	5 Classrooms 51-56 - Farb_01-05 Building Exterior, West Wall	DWO-367-033	Drinking Fountain Bubbler	<5		
34	5 Classrooms 51-56 - Farb_01-05 Classroom - 51T Ind Study, North Wall	DWO-367-034	Drinking Fountain Bubbler	5.35		
35	5 Classrooms 51-56 - Farb_01-05 Classroom - 53T Ind Study, West Wall	DWO-367-035	Drinking Fountain Bubbler	4.99		
36	5 Classrooms 51-56 - Farb_01-05 Classroom - 54T Ind Study, West Wall	DWO-367-036	Drinking Fountain Bubbler	3.53		
37	5 Classrooms 51-56 - Farb_01-05 Classroom - 56T Ind Study, South Wall	DWO-367-037	Drinking Fountain Bubbler	15.50		
38	Portable B08 - Farb Classroom - B08, West Wall	DWO-367-038	Drinking Fountain Bubbler	6.04		
39	Admin/Kitchen/Library/Supply - Farb_01-01 Counseling Center, west wall of hallway, across from site	DWO-367-039	Drinking Fountain Bubbler	19.8		
40	Admin/Kitchen/Library/Supply - Farb_01-01 Counseling Center, west wall of hallway, across from site	DWO-367-040	Drinking Fountain Bubbler	19.4		
41	600 Multi-Purpose/Lockers/Science - Farb_02-06 Faculty Workroom - WRK1,	DWO-367-041	Faucet - Removed Prior to Testing			
42	Admin/Kitchen/Library/Supply - Farb_01-01 Staff Kitchen, West Wall	DWO-367-042	Faucet	0.82		
43	1 Admin/Kitchen/Library/Supply - Farb_01-01 Kitchen, south wall, right	DWO-367-043	Spray Faucet	<5		



Facility: Farb MS Report Type: Progress Report Date of Report: 5/9/2019

Location	DWO No	Туре	Initial		Clearance
Location			Result*	Taken**	Result

*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5ppb. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Inital result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.