Site:	Hover High School	Report Date:	04/13/18
Sampler:	SDUSD - Safety Office	Analyzed By:	EnviroMatrix Analytical, Inc

Federal Action Level (AL) is 15 parts per billion (PPB). District AL is 5 PPB.

Green shading = below District & Federal Action Levels
Yellow shading = below Federal Action level/Above District Action Level
Red Shading = above Federal Action Level

Sample ID	Sample Location	Lead Results	Units	Type of Fixture
1	200 Bldg, 1st Floor Interior Hallway, E-Wall near 204, mid bldg, L-bubbler	.084	ug/L	DB
2	200 Bldg, 1st Floor Interior Hallway, E-Wall near 204mid bldg, R-bubbler (Previously Sampled)		ug/L	DB
3	200 Bldg, 2nd Floor Interior Hallway, E-Wall near 254, mid bldg, L-bubbler	.13	ug/L	DB
4	200 Bldg, 2nd Floor Interior Hallway, E-Wall near 254, mid bldg, R-bubbler	.23	ug/L	DB
5	300 bldg, upstairs hall west end single fountain	4.3	ug/L	DB
6	Kitchen at double sink N/E wall, Previously Sampled)		ug/L	KF
7	Kitchen at double dish washing sink N/W (sink has flushing sign)		ug/L	KF
8	Kitchen Serving Room off of hall dish washing sink (sink has flushing sign)	1.5	ug/L	KF
9	Cafeteria West wall single fountain	7.8	ug/L	DB
10	Cafeteria East wall single fountain	3.8	ug/L	DB
11	Outside-Cafeteria E wall Three bubbler fountain, L-Bubbler	1.7	ug/L	DB
12	Outside-Cafeteria E wall Three bubbler fountain, Center Bubler	2.1	ug/L	DB
13	Outside-Cafeteria E wall Three bubbler fountain, R-Bubbler (Previously Sampled)		ug/L	DB
14	Outside-Kitchen Service line windows-N-wall -L-Single bubbler fountain (Low flow)	2.3	ug/L	DB
15	Outside-Kitchen Service line windows-N-wall -R -Single bubbler fountain (Low flow)	.81	ug/L	DB
16	400 Bldg, Library(Temp. Admin) interior N-Wall near metal Detector & across from RR, L-Bubbler	.75	ug/L	DB
17	400 Bldg, Library(Temp Admin) interior N-Wall near metal Detector & across from RR, R-Bubbler	.32	ug/L	DB
18	Rm 551-Exterior-2nd Flr at North Wall	.65	ug/L	DB
19	Rm 551 (ASB RM) -Interior-2nd Flr-North Wall	1.5	ug/L	DB
20	Rm 551 (ASB RM) - Interior-2nd Flr-North Wall		ug/L	KF
21	601 (Old Woodshop), Interior E-Wall, bubbler, R-Side on trough	9.5	ug/L	DB
22	602 Health Office, 1st-Aid Rm, faucet	4.4	ug/L	NF
23	602 Health Office, Kitchen/break Rm faucet	2.4	ug/L	KF
24	602 Health Office, Left Detist Rm, faucet	4.6	ug/L	NF
25	602 Health Office, Right Detist Rm, faucet	4.7	ug/L	NF
26	602 Health Office, Exam Rm, W/NW side of bldg, faucet	7.0	ug/L	NF

Coding: DB=Drinking Water Bubbler; WC=Water Cooler; CF= Classroom Faucet; KF=Kitchen Faucet; NS=Nurse Faucet

Site:	Hover High School	Report Date:	04/13/18
Sampler:	SDUSD - Safety Office	Analyzed By:	EnviroMatrix Analytical, Inc

Federal Action Level (AL) is 15 parts per billion (PPB). District AL is 5 PPB.

Green shading = below District & Federal Action Levels

Yellow shading = below Federal Action level/Above District Action Level

Red Shading = above Federal Action Level

Sample ID	Sample Location	Lead Results	Units	Type of Fixture
27	602 Health Office, Exam Rm, NW side of bldg, faucet	5.9	ug/L	NF
28	602 Health Office, Exam Rm, N-side of bldg, faucet	4.6	ug/L	NF
29	602 Health Office, N-Hallway, S-wall Sink Station, near reception	4.3	ug/L	NF
29B	602 Health Office, Center of Room, East Hallway	1.5	ug/L	NF
30	603 Woodshop, Interior S-Wall, Bubbler R-Side in trough	5.8	ug/L	DB
31	ROTC-South Entrance-Interior-North Wall	5.6	ug/L	DB
32	ROTC-East Entrance-Interior Restroom-North Wall	1.0	ug/L	DB
33	Rm 701-Exterior/1st Flr at South Wall-L Bubbler	11.0	ug/L	DB
34	Rm 701-Exterior/1st Flr at South Wall-R Bubbler	3.5	ug/L	DB
35	Rm 703A Interior, 1st Flr at East Wall, L-Sink Faucet		ug/L	KF
36	Rm 703A-Interior, 1st Flr at East Wall, R-Sink Faucet		ug/L	KF
37	900 Bldg-Exterior, 2nd Flr-South Wall-L Bubbler	.33	ug/L	DB
38	900 Bldg-Exterior, 2nd Flr-South Wall-R Bubbler (Prev Sampled)		ug/L	DB
39	Rm 903-Interior, 2nd Flr at East Wall-far Left	.58	ug/L	KF
40	Rm 903-Interior, 2nd Flr at East Wall-Middle Left	.25	ug/L	KF
41	Rm 903-Interior, 2nd Flr at East Wall-Middle Right	1.7	ug/L	KF
42	Rm 903-Interior 2nd Flr-East Wall-Far Right	.14	ug/L	KF
43	Rm 903-Inetrior 2nd Flr-South Wall	1.3	ug/L	KF
44	Rm 902-Interior 2nd Flr-North Wall	.3	ug/L	KF
45	Rm 902-Staff Rm-Interior 2nd Flr-South Wall (Verify)	1.8	ug/L	KF
46	Rm 901-Interior 2nd Flr-North Wall-Right (No Flow-No Sample)		ug/L	KF
47	Rm 901-Interior 2nd Flr-North Wall-Middle	.52	ug/L	KF
48	Rm 901-Interior 2nd Flr-North Wall-Left	.84	ug/L	KF
49	Rm 901-Interior 2nd Flr-East Wall		ug/L	KF
50	Back Quad area near 900 Bldg, Exterior/ Triple Bubbler-L	1.9	ug/L	DB
51	Back Quad area near 900 Bldg, Exterior/ Triple Bubbler-C	1.8	ug/L	DB

Coding: DB=Drinking Water Bubbler; WC=Water Cooler; CF= Classroom Faucet; KF=Kitchen Faucet; NS=Nurse Faucet

Site:	Hover High School	Report Date:	04/13/18
Sampler:	SDUSD - Safety Office	Analyzed By:	EnviroMatrix Analytical, Inc

Federal Action Level (AL) is 15 parts per billion (PPB). District AL is 5 PPB.

Green shading = below District & Federal Action Levels

Yellow shading = below Federal Action level/Above District Action Level

Red Shading = above Federal Action Level

Sample ID	Sample Location	Lead Results	Units	Type of Fixture
52	Back Quad area near 900 Bldg, Exterior/ Triple Bubbler-R	1.4	ug/L	DB
53	1000 Bldg, Exterior/East Wall/2nd Floor@ Rm1055	.83	ug/L	DB
54	1000 Bldg,Main Prep Rm/South Wall		ug/L	CF
55	1100 BLDG TEACHERS LOUNGE RM (W WALL) Sink Faucet	ND	ug/L	CF
56	1100 BLDG TEACHERS LOUNGE RM (W WALL) Gooseneck		ug/L	CF
57	1100 BLDG W EXTERIOR (E WALL/OUTSIDE RM 1152)	1.1	ug/L	DB
58	1100 BLDG RM 1102 (S WALL) Check if used	4.6	ug/L	CF
59	1100 BLDG W EXTERIOR (E WALL)	1.8	ug/L	DB
60	1200 BLDG 1ST FLR S HALLWAY (W WALL) (No Sample-No Flow)		ug/L	DB
61	1200 BLDG 1ST FLR N HALLWAY (W WALL) Low flow (No Sample)		ug/L	DB
62	1200 BLDG 2ND FLR N HALLWAY (W WALL) (No Sample-No Flow)		ug/L	DB
63	1200 BLDG S EXTERIOR	1.3	ug/L	DB
64	BIG GYM (SW WALL) - WATER TURNED OFF (Don't Sample)		ug/L	DB
65	BIG GYM CUSPIDOR (SE WALL) - DON'T SAMPLE		ug/L	
66	BIG GYM E MAIN ENTRANCE (SE WALL/BY THE STAIRS)		ug/L	ÐB
67	BIG GYM (NE WALL) - WATER TURNED OFF (DON'T SAMPLE)		ug/L	DB
68	BIG GYM CUSPIDOR (SE WALL) - DON'T SAMPLE		ug/L	
69	BIG GYM N BOYS LOCKER RM (W WALL)	1.2	ug/L	DB
70	BIG GYM TRAINING RM SINK (S WALL) Enter through Team Rm/ Connected To Ice Maker	1	ug/L	CF
71	BIG GYM TRAINING RM SINK (N WALL) Enter by Team Rm		ug/L	CF
72	BIG GYM W EXTERIOR, L Bubbler	1.6	ug/L	DB
73	BIG GYM W EXTERIOR, R Bubbler	1.2	ug/L	DB
74	SMALL GYM N FITNESS RM (W WALL)		ug/L	DB
75	SMALL GYM (NW WALL)	1.1	ug/L	DB
76	SMALL GYM S GIRLS LOCKER RM (E WALL) - WATER TURNED OFF		ug/L	DB
77	SM GYM S GIRLS LOCKER RM OFFICE' BACK RM (S WALL) Door Label "UPS INSIDE"		ug/L	CF

Site:	Hover High School	Report Date:	04/13/18
Sampler:	SDUSD - Safety Office	Analyzed By:	EnviroMatrix Analytical, Inc

Federal Action Level (AL) is 15 parts per billion (PPB). District AL is 5 PPB.

Green shading = below District & Federal Action Levels
Yellow shading = below Federal Action level/Above District Action Level
Red Shading = above Federal Action Level

Sample ID	Sample Location	Lead Results	Units	Type of Fixture
78	SMALL GYM S EXTERIOR L Bubbler (N WALL)	1.2	ug/L	DB
79	SMALL GYM S EXTERIOR C Bubbler (N WALL) Low Flow (No Sample)		ug/L	DB
80	SM GYM S EXT, R-Bubbler (N WALL) - PREVIOUSLY SAMPLED		ug/L	DB
81	Interior/ Bungalow A15/ West Wall Faucet		ug/L	KF
82	Interior/ Bungalow A15/ West Wall, Faucet		ug/L	CF
83	Interior/ Bungalow A15/ West Wall, Bubbler	3.0	ug/L	DB
84	Interior/Bungalow A16/South Wall	6.9	ug/L	KF
85	Interior/Bungalow A11/Conference Room-West Wall		ug/L	CF
86	Concession Stand-Exterior-NorthEast Wall, Left bubbler (Home Side)	.19	ug/L	DB
87	Concession Stand-Exterior-NorthEast Wall, R-bubbler (Home Side)	.19	ug/L	DB
88	Concession Stand-Interior-North Wall (Home Side)	.54	ug/L	KF
89	Concession Stand-Exterior-North Wall-L bubbler (visitor)	.11	ug/L	DB
90	Concession Stand-Exterior-North Wall-R bubbler (Visitor)	.11	ug/L	DB
91	Concession Stand-Interior-South Wall (Visitor)	1.7	ug/L	KF
92	800 Bldg, West Wall, Single Faucet		ug/L	CF
93	660 Bldg, Northwest Wall, Small Room, Single Faucet next Refrig.	1.5	ug/L	KF
94	500 Bldg, Room 501, South Wall, Classroom Faucet	.32	ug/L	CF
95	Big Gym, Boys Locker, Office, Coaches Lockerroom, East Wall	3.9	ug/L	CF
96	Softball Field, Southeast Dugout, Northeast Wall Left	.033	ug/L	DB
97	Softball Field, Southeast Dugout, Northeast Wall Right	.038	ug/L	DB
98	Softball Field, Northeast Dugout, Southeast Wall Left	.043	ug/L	DB
99	Softball Field, Northeast Dugout, Southeast Wall Right	.031	ug/L	DB
100	Baseball Field, Southwest Dugout, Southeast Wall, Left	.053	ug/L	DB
101	Baseball Field, Southwest Dugout, Southeast Wall, Right	.056	ug/L	DB
102	Baseball Field, South Dugout, West Wall, Left	.051	ug/L	DB
103	Baseball Field, South Dugout, West Wall, Right	.083	ug/L	DB

Coding: DB=Drinking Water Bubbler; WC=Water Cooler; CF= Classroom Faucet; KF=Kitchen Faucet; NS=Nurse Faucet

Site:	Hover High School	Report Date:	04/13/18
Sampler:	SDUSD - Safety Office	Analyzed By:	EnviroMatrix Analytical, Inc

Federal Action Level (AL) is 15 parts per billion (PPB). District AL is 5 PPB.

Green shading = below District & Federal Action Levels
Yellow shading = below Federal Action level/Above District Action Level
Red Shading = above Federal Action Level

Sample ID	Sample Location	Lead Results	Units	Type of Fixture
104	700 Bldg, Rm 702, Lower Flr, Art Sink, far left faucet	1.4	ug/L	CF